| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|------|--|---|---------------------|---------|------------------|
| S1 | 199 | 702/85.ccls. and calibrating | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:27 |
| S2 | 2 | "6091281".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:31 |
| S3 | 2 | "5764048".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:39 |
| S4 | 6 | 455/130.ccls. and calibrating | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:40 |
| S5 | 1 | 455/63.3.ccls. and calibrating | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:41 |
| S6 | 7 | 455/67.13.ccls. and calibrating | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:59 |
| S7 | 0 | remote near calibrating near measuring near instrument | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 13:59 |
| S8 | 1883 | remote and calibrating and measuring and instrument | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:00 |
| S9 | 621 | (remote and calibrating and measuring and instrument) and converting | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:08 |

| S10 | 478 | ((remote and calibrating and measuring and instrument) and converting) and standard | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:08 |
|-----|------|--|---|----|----|------------------|
| S11 | 474 | (((remote and calibrating and measuring and instrument) and converting) and standard) and reference | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:08 |
| S12 | 1244 | (remote and calibrating and measuring and instrument) and frequency | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:09 |
| S13 | 366 | ((remote and calibrating and measuring and instrument) and converting) and (((remote and calibrating and measuring and instrument) and converting) and standard) and ((((remote and calibrating and measuring and instrument) and converting) and standard) and reference) and ((remote and calibrating and measuring and instrument) and frequency) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | ON | 2004/11/05 14:09 |